

B58 Gen1 platforms minor modifications to the cowl brace is required as shown here.

The cowl brace on the right side requires a notch and modification of the plastic cover.







